No. 348.—IRELAND—EAST COAST.

Kingstown Harbour—Amended Description of Lights.

Particulars.—The characters of the undermentioned lights in Kingstown Harbour are as described below:—

1. Name.—Carlisle Pier.

Position.—On head of pier; lat. 53°  $17\frac{3}{4}$ ′ N., long. 6°  $7\frac{3}{4}$ ′ W.

Character.—Fixed.

Elevation.—22 feet.

Visibility.—One mile.

Sectors.—Red from S. 32° E., through south and west, to N. 57° W.; white in other directions.

Description of building.—A stone structure 7 feet above high water.

Order or power.-Ordinary gas lamp.

2. Name.—Traders Wharf.

Position.—On head of wharf.

Character.—Fixed.

Elevation.—24 feet.

Visibility.—One mile.

Sectors.—Green from N. 20° E., through east, to S. 74° E.; white from S. 74° E., through south, to S. 20° W.; green from S. 20° W., through west, to N. 60° W.; white from N. 60° W., through north, to N. 20° E.

Description of building.—A stone structure 12 feet above high water.

Light power.—Gas lamp, under 100 candles. Variation.—19° W.

Chart affected.—No. 1471, Kingstown Harbour.

Publications.—List of Lights, Part I, 1908, No. 1117, and Remarks; Irish Coast Pilot, 1902, page 161; and Supplement, 1905.

Authority.—Dublin Public Works, 27th February, 1908.

No. 349.—BALTIC, GERMANY—KIEL BAY.

Eckernförder Bucht—Position of Measured Mile Buoy Altered.

Particulars.—The Measured Mile Buoy No. 2 in Eckernförder Bucht has been moved to the undermentioned position.

Position.—Lat. 54° 28′ 50" N., long. 9° 59′ 30" E.

Charts Affected.—No. 33, Eckernförder Bucht; No. 2117, Kiel Bay.

Publications.—Baltic Pilot, Part I, 1904, page 468; and Supplement, 1907. Notice to Mariners, No. 1587 of 1907.

Authority.—Berlin Notice, No. 394 of 1908.

No. 350.—ADRIATIC—GULF OF VENICE.

Trieste Harbour-Mooring Buoy Withdrawn.

Particulars.—The undermentioned mooring buoy in Trieste Harbour has been withdrawn.

Position.—About 3 cables N. 33° E. from Santa Teresa Light; lat. 45° 39¼' N., long. 13° 45½' E. Variation.—5° W. Chart affected.—No. 1434, Gulf of Trieste, with Plan of Trieste.

Publication.—Mediterranean Pilot, Vol. III, 1899, page 127.

Authority.-Pola Notice, No. 175 of 1908.

## No. 351,—ADRIATIC—DALMATIA, PORT ROGOSNIZZA.

Mulo Islet Light-Red Sector Removed.

Particulars.—On 1st March, 1908, the following alteration would be made in the undermentioned light in the approach to Rogosnizza.

Name.—Mulo Islet.

Position.—Lat. 43° 31' N., long. 15° 55½' E.

Alteration.—The red sector would be removed, the light will then show white fixed from all directions.

Visibility.-14 miles.

Chart affected.—No. 2774, Grossa Island to Zirona Channel.

Publications.—List of Lights, Part V, 1908, No. 819; Mediterranean Pilot, Vol. III. 1899. page 229; and Supplement, 1904; Notice to Mariners, No. 1913 of 1907.

Authority.—Pola Notice, No. 177 of 1908.

## No. 352.—ADRIATIC—ISTRIA.

Cittanuova-Mooring Buoy Established.

Particulars.—A mooring buoy has been established in Cittanuova Harbour as follows:—

Position.—In a depth of 3 fathoms in a position from which the pier light bears S. 1° E., distant half a cable, and San Antonio Chapel east; lat. 45° 19½' N., long. 18° 33½' E.

Variation .- 9° W.

Chart affected.—No. 1559, Plan of Port Quieto.

Publication.—Mediterranean Pilot, Vol. III, 1899, page 134.

Authority.—Pola Notice, No. 176 of 1908.

## No. 353.—ENGLAND, EAST COAST— THE WASH.

Freeman Channel—Light-Vessel Withdrawn,
Alteration in Buoys.

Particulars.—The undermentioned alterations in the lighting and buoyage of Freeman Channel and Boston Deep have been made as follows:—

1. Freeman Channel.

Position.—Lat. 52° 584' N., long. 0° 124' E.

Alteration.—a. Freeman Channel Light-vessel exhibiting two white fixed lights has been withdrawn.

- b. The black conical F. No. 3 has been replaced by a conical light-buoy, painted black, exhibiting a red occulting light.
  - 2. Boston Deep.

Position.—About 2½ miles N. 87° W. from former position of Freeman Channel Light-vessel,