

Firth; No. 2180*b*, Orkney Islands, southern portion; No. 2397*b*, Scotland, north and east coasts; No. 2181, Dunbeath Harbour to Thurso Bay; No. 2182*b*, North Sea, northern sheet.

Publications.—List of Lights, Part I, 1910, page 109; North Sea Pilot, Part I, 1903, page 210; North Sea Pilot, Part II, 1905, page 71.

Authority.—Commissioners of Northern Lighthouses Notice, No. 12 of 1910.

No. 1253.—NEW EDITION OF A CHART.

Chart No. 2397a.

A new edition of Chart No. 2397*a*, Scotland, north and east coasts, dated August, 1910, has been published. The following temporary Notices to Mariners, which affect this chart, are still in force:—

No. 813 of 1910, North Carr light-vessel temporarily replaced by reserve light-vessel; No. 1209 of 1910, River Tay fairway buoy temporarily replaced by unlighted buoy.

No. 1254.—FRANCE, NORTH COAST.

Plateau des Minquiers—Whistle-buoy Temporarily Replaced by Bell-buoy.

Position.—On south-western side of Plateau; lat. $48^{\circ} 53\frac{1}{2}'$ N., long. $2^{\circ} 26\frac{1}{4}'$ W.

Description of bell-buoy.—A black conical buoy with cylindrical topmark.

Remarks.—Further notice will be given when the whistle-buoy has been replaced.

Charts temporarily affected.—No. 2100, Plateau des Minquiers; No. 2669, Channel Islands and adjacent Coast of France; No. 2675*b*, English Channel, middle sheet; No. 1598, English Channel.

Publication.—Channel Pilot, Part II, 1906, page 160.

Authority.—Paris Notice, No. 2203 of 1910.

No. 1255.—CANADA, NOVA SCOTIA—
BAY OF FUNDY.

Lurcher Shoal Light-Vessel—To be temporarily replaced by Light-and-Whistle-Buoy.

Position.—Lat. $43^{\circ} 49\frac{1}{2}'$ N., long. $66^{\circ} 32'$ W.

Date of replacement.—On or about the 20th September, 1910.

Description of light-and-whistle-buoy.—A red buoy, exhibiting an occulting white light.

Remarks.—Further notice will be given when the light-vessel has been replaced on her station.

Charts temporarily affected.—No. 352, Bay of Fundy, Sheet I; No. 1651, Nova Scotia, &c.; No. 2670, Halifax to the Delaware.

Publications.—List of Lights, Part VIII, 1910, No. 692; S.E. Coast of Nova Scotia, &c., 1903, page 225; Revised Supplement, 1908.

Authority.—Ottawa Notice, No. 210 of 1910.

No. 1256.—FRANCE, WEST COAST—
ROCHEBONNE PLATEAU.

La Congr e Lighthouse Works—Vessels Withdrawn.

Position.—La Congr e Rock, lat. $46^{\circ} 12'$ N., long. $2^{\circ} 25\frac{1}{4}'$ W.

Details.—The construction of the lighthouse on La Congr e, Rochebonne Plateau, having been suspended for the winter season, the vessels described below have been withdrawn.

(a) The hulk (used as a store ship) with three masts, painted red, with "Rochebonne" on each side, which at night exhibits only the lights of a vessel at anchor, moored about $1\frac{1}{4}$ miles, N. 37° E., from La Congr e.

(b) The small steam vessel and two lighters, carrying anchor lights, moored during the night about $1\frac{1}{4}$ miles N. 60° E., from La Congr e.

Remarks.—The eight white prismatic mooring buoys will be removed later.

Variation.— 15° W.

Charts affected.—No. 2648, Pte. de la Coubre to Les Sables d'Olonne; No. 1104, Bay of Biscay.

Publications.—West Coasts of France, &c., 1910, page 295; Notice to Mariners, No. 735 of 1910.

Authority.—Paris Notice, No. 2204 of 1910.

No. 1257.—KOREA, SOUTH COAST.

Stanley Island—Light Established.

Position.—On north-western extreme of island; lat. $34^{\circ} 13' 40''$ N., long. $126^{\circ} 46' 15''$ E., on Chart No. 3365.

Character.—A flashing white light every three seconds, showing thus:—Flash, $\frac{3}{10}$ second; eclipse, $2\frac{7}{10}$ seconds.

Elevation.—200 feet.

Visibility.—10 miles, from the bearing N. 35° E., through east, &c., to N. 80° W.

Order.—6th.

Structure.—White circular tower, 15 feet in height to centre of lantern.

Remarks.—The light is unwatched.

Variation.— 4° W.

Charts affected.—No. 3365, Port Hamilton to Mackau Group; No. 104, Korean Archipelago, Southern Portion; No. 1262, Hongkong to the Gulf of Liau Tung; No. 2347, Nipon, Kiusiu, and Shikoku, &c.; No. 3480, Shantung Promontory to Nagasaki.

Publications.—List of Lights, Part VI, 1910, page 171; Japan, Korea, &c., 1904, page 92.

Authority.—Seoul Notice, No. 115, 5th July, 1910.

No. 1258.—CHINA, EAST COAST—YANG
TSE KIANG.

(1) *South Channel—Alteration in Position of Kiutoan Light-Vessel.*

New position.—At a distance of 3 miles, S. 52° E., from former position; lat. $31^{\circ} 12' 3''$ N., long. $121^{\circ} 51' 0''$ E., on Chart No. 1602.

Remarks.—On the 30th July, 1910, the light-vessel was to be withdrawn for repair, and her position, as given above, was to be temporarily marked by a light-buoy, painted red, exhibiting