

## THIRD SCHEDULE.

*Orders Revoked.*

No.	Date.	Subject or Short Title.
	1907.	
7345	27 September	Declaration of the following Swine-Fever Infected Area, viz., An Area comprising the administrative county of the Isle of Wight.
7346	28 September	
	1908.	
7392	7 January ..	Isle of Wight (Swine-Fever Order) of 1908.

Copies of the above Order can be obtained on application to the Secretary, Board of Agriculture and Fisheries, 4, Whitehall Place London, S.W.

## NOTICES TO MARINERS.

(No. 541 to 547 of the year 1908).

[The Astronomical positions are approximate unless otherwise stated. The bearings are Magnetic, and those relating to lights are given from seaward. The visibility of lights is that in clear weather. Fog signals are sounded during thick or foggy weather unless otherwise stated. The depths are given at low-water ordinary springs. The heights are given above high water.]

No. 541.—SCOTLAND, WEST COAST—  
SOUND OF IONA.*Ruadh Sgeir—Beacon Established.*

Particulars.—A beacon of the undermentioned description has been established on Ruadh Sgeir, Iona Sound.

Position.—Lat. 56° 15' N., long. 6° 21' W.

Description.—A stone beacon surmounted by a cross.

Note.—It has been placed on the chart on the easternmost rock.

Charts affected.—No. 2617, Sound of Iona; No. 2515, Mull of Cantyre to Ardnamurchan.

Publication.—Sailing Directions for the West Coast of Scotland, 1902, page 159.

Authority.—His Majesty's ship Swiftsure, Hydrographic Note, No 1 of 1908.

No. 542.—NORTH PACIFIC—CAROLINE  
ISLANDS—PONAPI.

*Port Santiago (Langar Harbour)—Non-Existence of Mooring Buoys.*

Particulars.—The two undermentioned mooring buoys in Port Santiago do not now exist.

Former positions.—1½ cables and 6¼ cables respectively south-westward from Langar Island Pierhead; Langar Pierhead, lat. 6° 59½' N., long. 158° 17½' E.

Note.—Port Santiago is also known as Langar Harbour; the latter has been placed on the chart as an alternative name.

Chart affected.—No. 981, 'Seniavina Islands, with plan of Port Santiago.

Publication.—Pacific Islands, Vol. I, 1900, page 421; Supplement, 1903.

Authority.—Berlin Notice, No. 728 of 1908.

No. 543.—MEDITERRANEAN—ITALY, WEST  
COAST.*Port Salerno—Shoal in.*

Particulars.—A shoal exists on the northern side of the entrance to Port Salerno.

Position.—Old Breakwater Light bearing S. 79° W., distant 1 cable. Manfredi Mole Green Light, N. 69° W.; lat. 40° 40½' N., long. 14° 45½' E.

Depth.—9 feet.

Variation.—8° W.

Chart affected.—No. 1596. Plans:—Port Salerno; Salerno Bay.

Publication.—Mediterranean Pilot, Vol. II, 1905, page 272.

Authority.—Genoa Notice, No. 80 of 1908.

No. 544.—MEDITERRANEAN—ITALY,  
WEST COAST.*Africa Rock Light—Character Temporarily  
Altered.*

Particulars.—In consequence of damage to the occulting apparatus, the white occulting light shown from the lighthouse on Africa rock will show white fixed until further notice.

Position.—Lat. 42° 21½' N., long. 10° 4' E.

Charts temporarily affected.—No. 158, Cape Cavallo to Civita Vecchia; No. 1131, Corsica; No. 1780, Gulfs of Lyons and Genoa; No. 676, Tyrrhenian Sea.

Publications.—List of Lights, Part V., 1908, No. 384; Mediterranean Pilot, Part II., 1905, page 219.

Authority.—Genoa Notice, No. 81 of 1908.