

(a) Review the arrangements for sampling the final water. To be completed by 31st July 1997.

(b) Review the provision, operation and control of the disinfection system. To be completed by 31st December 1997.

(c) Carry out enhanced monitoring at the treatment works consisting of daily (Monday to Friday inclusive) bacteriological monitoring of the water at the inlet and the final water outlet. To be completed by 31st December 1997.

(d) Inspect the final water break tank and carry out any remedial work identified. To be completed by 31st December 1997.

(e) Report to DWI the outcome of the reviews in (a) and (b), the monitoring data in (c) and the conclusions on the need for further remedial actions. To be completed by 31st January 1998.

(f) Carry out any necessary remedial actions identified in (a), (b) and (c). To be completed by 31st March 1998.

- (4) is satisfied that Mid Southern Water plc has given and is complying with an undertaking to take all such steps as appear to the Secretary of State for the time being to be appropriate to secure or facilitate compliance with the requirement of Regulation 3(7) of the Water Supply (Water Quality) Regulations 1989.

Authorised by the Secretary of State to sign in that behalf:

M. Rouse, Chief Inspector, Drinking Water Inspectorate. DWI Ref. No. MS 022. Ref. No. E1619/01/DWI.

9th September 1997.

(2 SI)

WATER INDUSTRY ACT 1991, SECTION 19(1)(b)

Consumers supplied by Mid Southern Water plc, in Camberley, Sandhurst, Farnborough and Fleet might be affected by improvement work at Bray Water Treatment Works. The following briefly explains the content of the legal notice below.

Water supplied from this works does not always meet the drinking water quality standard for total coliforms. These failures do not make the water unsafe to drink at any time.

The Drinking Water Inspectorate (DWI) acting for the Secretary of State has required the Company to take action to improve the quality of the supply to consumers by 31st March 1998.

Details of this work are on the Company's public record which can be seen at any of its offices, open to the public during normal working hours. You can find out about the work and whether your water supply is affected by telephoning the Company on 01252-835031, or writing to them at Frimley Green, Camberley, Surrey GU16 6HZ, quoting DWI reference number MS 023.

This notice has been issued by the Drinking Water Inspectorate, Romney House, Marsham Street, London SW1P 3PY.

WATER INDUSTRY ACT 1991, SECTION 19(1)(b)

The Secretary of State for the Environment, Transport and the Regions:

1. is satisfied that Mid Southern Water plc, "the Company", in supplying water from Bray Water Treatment Works is likely to do so again its duty to supply wholesome water under section 68(1)(a) of the Water Industry Act 1991, and the requirement of regulation 3(7) of the Water Supply (Water Quality) Regulations 1989, that water supplied should not contain total coliforms;
2. has notified Mid Southern Water plc on 18th April 1997, that he is considering making in relation to the Company an enforcement Order under section 18 of the Water Industry Act 1991;
3. notes that Mid Southern Water plc has, on 4th July 1997, given an undertaking under section 19(1)(b) of the Water Industry Act 1991 to take the following steps by the dates shown:
 - (a) review the arrangements for sampling the final water, to be completed by 31st July 1997;
 - (b) review the provision, operation and control of the disinfection system, to be completed by 31st December 1997;
 - (c) carry out enhanced monitoring at the treatment works consisting of daily (Monday to Friday inclusive) bacteriological monitoring of the treatment process at the raw, clarified, sand filtered, GAC filtered and final water stages, to be completed by 31st December 1997;
 - (d) report to DWI the outcome of the reviews in (a) and (b), the monitoring data in (c) and the conclusions on the need for further remedial actions, to be completed by 31st January 1998;
 - (e) carry out any necessary remedial actions identified in (a), (b) and (c), to be completed by 31st March 1998;

4. is satisfied that Mid Southern Water plc has given, and is complying with, an undertaking to take all such steps as appear to the Secretary of State for the time being to be appropriate to secure or facilitate compliance with the requirement of Regulation 3(7) of the Water Supply (Water Quality) Regulations 1989.

Authorised by the Secretary of State to sign in that behalf.

M. Rouse, Chief Inspector, Drinking Water Inspectorate. (Ref. E1620/01/DWI.)

9th September 1997.

(3 SI)

WATER INDUSTRY ACT 1991, SECTION 19(1)(b)

Consumers supplied by Mid Southern Water plc, in Badshott Lea might be affected by improvement work at Badshott Lea Water Supply Zone. The following briefly explains the content of the legal notice below.

Water supplied in this zone does not always meet the drinking water quality standard for total coliforms. These failures do not make the water unsafe to drink at any time.

The Drinking Water Inspectorate (DWI) acting for the Secretary of State has required the Company to take action to improve the quality of the supply to consumers by 31st January 1998.

Details of this work are on the Company's public record which can be seen at any of its offices, open to the public during normal working hours. You can find out about the work and whether your water supply is affected by telephoning the Company on 01252-835031, or writing to them at Frimley Green, Camberley, Surrey GU16 6HZ, quoting DWI reference number MS 024.

This notice has been issued by the Drinking Water Inspectorate, Romney House, Marsham Street, London SW1P 3PY.

WATER INDUSTRY ACT 1991, SECTION 19(1)(b)

The Secretary of State for the Environment, Transport and the Regions:

1. is satisfied that Mid Southern Water plc, "the Company", in supplying water in Badshott Lea Water Supply Zone is contravening and is likely to do so again its duty to supply wholesome water under section 68(1)(a) of the Water Industry Act 1991, and the requirement of regulation 3(6) of the Water Supply (Water Quality) Regulations 1989, that water supplied should not contain total coliforms;
2. has notified Mid Southern Water plc on 18th April 1997, that he is considering making in relation to the Company an enforcement Order under section 18 of the Water Industry Act 1991;
3. notes that Mid Southern Water plc has, on 4th July 1997, given an undertaking under section 19(1)(b) of the Water Industry Act 1991 to take the following steps by the dates shown:
 - Investigate possible cause of bacteriological contamination by:
 - (a) on each compliance sampling occasion, take a compliance sample and two further samples from adjacent properties served from the same main for bacteriological examination, to be completed by 31st December 1997;
 - (b) take an additional large volume sample from the compliance sample point for bacteriological examination, to be completed by 31st December 1997;
 - (c) on each occasion when coliforms are detected in any of the sample in (a) or (b), take additional samples and tap swabs as indicated in Information Letter, 3/95, for bacteriological examination, to be completed by 31st December 1997;
 - (d) report the outcome of the monitoring data obtained in (a), (b) and (c) and the conclusions on the need for further remedial action, to be completed by 31st January 1998;
 - (e) undertake any appropriate remedial action in response to coliform contamination indicated in (a), (b) and (c), to be completed by 31st January 1998;
4. is satisfied that Mid Southern Water plc has given, and is complying with, an undertaking to take all such steps as appear to the Secretary of State for the time being to be appropriate to secure or facilitate compliance with the requirement of Regulation 3(7) of the Water Supply (Water Quality) Regulations 1989.

Authorised by the Secretary of State to sign in that behalf.

M. Rouse, Chief Inspector, Drinking Water Inspectorate. (Ref. E1621/01/DWI.)

9th September 1997.

(4 SI)